

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-02 To (mo./yr.) 1-1-03
2. DOGM File Number (Mine No): M 1043/021
3. Mine Name: BROWNS CANYON STONE QUARRY
4. Mineral(s) Mined (or permitted to mine): SANDSTONE
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
SW 1/4, NW 1/4, 1/4, Section 21, Township 15, Range SE  
NW 1/4, SW 1/4, 1/4, Section 21, Township 15, Range SE  
1/4, 1/4, 1/4, Section, Township, Range
7. Name of Operator or Company: BMW STONE INC
8. Permanent Street Address: 2565 So. STATE RD. 32  
City, State, Zip: WASHIP UTAH 84017  
Phone: 801-573-0562 Fax: 435-336-9621
9. Company Representative (or designated operator):  
Name: MARK WILLES  
Title: President  
Business Address: 2565 So. ST. RD. 32  
City, State, Zip: WASHIP, UT 84017  
Phone: 435-336-9620 Fax: 435-336-9621  
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? \_\_\_\_\_
3. If yes - how much ore or mineral was mined? 11,000 CUBIC YARDS

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

*The stone is quarried from the outcrops and processed into building and landscape products. Approximately 15,000 cubic yards of material was moved.*

5. How much additional acreage was disturbed during the past year? 1

6. How much acreage was reclaimed during the past year? 0

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

8. What is the **total** disturbed acreage of entire project at years end? 8.4

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

*We are still mining.*

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

**III. Additional Information - R647-4-121.2 and .3**

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

**IV. Signature Requirement**

**I hereby certify that the foregoing is true and correct.**

Name (Typed or Print): MARK WILLES

Title of Operator: President

Signature of Operator: Mark Willes

Date: 1-18-03